



QUALIDADES

limites de diâmetros (mm)	7		8		9		10		11	
	h7	k7	h8	k8	h9	k9	h10	k10	h11	k11
	1 a 3	0	+10	0	+14	0	+25	0	+40	0
acima 3 a 6	-10	0	-14	0	-25	0	-40	0	-60	0
	0	+13	0	+18	0	+30	0	+48	0	+75
acima 6 a 10	-12	+1	-18	0	-30	0	-48	0	-75	0
	0	+16	0	+22	0	+36	0	+58	0	+90
acima 10 a 18	-15	+1	-22	0	-36	0	-58	0	-90	0
	0	+19	0	+27	0	+43	0	+70	0	+110
acima 18 a 30	-18	+1	-27	0	-43	0	-70	0	-110	0
	0	+23	0	+33	0	+52	0	+84	0	+130
acima 30 a 50	-21	+2	-33	0	-52	0	-84	0	-130	0
	0	+27	0	+39	0	+62	0	+100	0	+160
acima 50 a 80	-25	+2	-39	0	-62	0	-100	0	-160	0
	0	+32	0	+46	0	+74	0	+120	0	+190
acima 80 a 120	-30	+2	-46	0	-74	0	-120	0	-190	0
	0	+38	0	+54	0	+87	0	+140	0	+220
	-35	+3	-54	0	-87	0	-140	0	-220	0